

		Type	L #	Hits	Search Text	DBs	Time Stamp	Error Count	Error Definition
1	BRS	L8	569		((abrasi\$2 adj2 free) or (slurry near3 (free or without or "none" or "no")) same (polish\$3 or planariz\$5)) and semiconductor	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/01/25 11:11	0	
2	BRS	L15	210	8 and 438/\$.ccls.		USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/01/25 13:18	0	
3	BRS	L22	210	15 and Pd<=19980831		USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/01/25 11:14	0	
4	BRS	L29	26	15 and @Pd<=19980831		USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/01/25 12:00	0	
5	BRS	L36	0	"A New Abrasive-Free, Chemical-Mechanical-Polishing Technique for Aluminum Metallization of ULSI Devices"		USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/01/25 12:04	0	
6	BRS	L43	84	(AF or AFP) same (cmp or polish\$3)		USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/01/25 12:05	0	
7	BRS	L50	184	15 not 29		USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/01/25 12:52	0	
8	BRS	L57	49	8 and 252/\$.ccls.		USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/01/25 13:18	0	

	Type	L #	Hits	Search Text	DBs	Time Stamp	Er C ro m m e n t i s o n
9	BRS	L64	2217	57 mot 50	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/01/25 13:21	0
10	BRS	L71	24	57 not 50	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/01/25 13:18	0